

Parish Report

Enquiry Number	Cust Type Name	Logged Date	Street Location Details	Subject Name Service Name	Enquiry Desc	Enq Status Name	Job Start Date	O/S Flag	Latest Update
16210220	Parish Representative	30/07/2008	CHAUCER WAY land at chaucer way larkfield- triangular piece of land where the public path and cycleway from new hythe lane (mr94a) meets chaucer way	z-Overgrown Hedge z-Vegetation	the land backs onto the walls of the houses in fielding drive adn was planted by the original developers by very prickly bushes. theres bushes havenot got very much larger and tend to grow out by path. they have prevented growth so the area neneath them is jus soil there wasno ther bushes of this species planted anywhere else on the estate the result is this area also looks untidy most of the year and really this sort of bush is unsuiable for this location particularly as it is now so large. it is suggested thattherefore they should be removed and a more suitable landscaping is provided	ENQ - Enquiry Resolved		N	Works completed.
10200954	Parish Representative	23/10/2008	LONDON ROAD On the verge east of the nursery school.	z-Unlit Bollard-Damaged/Miss. Carriageway/Road/Cycleway	Bollards have gone missing. The Parish Council has asked these be replaced as otherwis the parking on the verge and pavement is likely to start up again. Passed to Darren Poxon to inspect at 15:25pm on 24/10/08 - Claire Chewter.	JO - Works Completed	10/11/2008	N	Job progressed
10201135	Parish Representative	17/11/2008	NEW HYTHE LANE On the corner at Larkfield Village Hall where blackthorn bushes need severe cutting back.	Obstructing Highway Veg-Veg. Overgrown (not tree)	Letter received from Parish Clerk Val dated 5th Nov 08 - Stating on the corner at Larkfield Village Hall where blackthorn bushes need severe cutting back.	ENQ - No Action Required		N	Having Inspected the site hedges are not causing a h&s issue.
10201133	Parish Representative	17/11/2008	NEW HYTHE LANE In New Hythe Lane west side from the footpath into Cygnet Close down to the entrance to Larkfield Village Hall.	Obstructing Highway Veg-Veg. Overgrown (not tree)	Letter received from Parish Clerk Val Severn dated 5th Nov 08 - Problems with overgrown vegetation on footway, the Parish Council are particularly concerned with this location and request the path needs re-instating to its full width.	ENQ - Enquiry Resolved		N	Highways Definitions confirmed retaining wall and verge as KHS. Will be put forward for contract.
10201136	Parish Representative	17/11/2008	CHAUCER WAY In Chaucer Way near and at the entrance to the path to Larkfield Village Hall.	Obstructing Highway Veg-Veg. Overgrown (not tree)	Letter received from Parish Clerk Val dated 5th Nov 08 - Problems of overgrown veg on footway in Chaucer Way near and at the entrance to the path to Larkfield Village Hall.	ENQ - Enquiry Resolved		N	Verge at crossroad of paths at entrance to New Hythe Lane are maintained by TMBC
10201139	Parish Representative	17/11/2008	REDWING CLOSE	Obstructing Sign/Light/TS Veg-Veg. Overgrown (not tree)	Letter received from Parish Clerk Val dated 5th Nov 08 - The footpath (not definitive) from Redwing Close footbridge over the M20 down east of Fielding Drive where clearance is needed to make street lighting more useful. This is has been reported on many occasions and promises were given that work will take place - nothing has happened. It would be helpful if we could meet someone to show these spots on site please. Could this be arranged?	ENQ - Enquiry Reassigned		Y	

Parish Report

Enquiry Number	Cust Type Name	Logged Date	Street Location Details	Subject Name Service Name	Enquiry Desc	Enq Status Name	Job Start Date	O/S Flag	Latest Update
10201388	Parish Representative	04/12/2008	GILLETTS LANE	Resurfacing enquiry Carriageway/Road/Cycleway	Transferred from Parish Spreadsheet Ref T/EM/08/004- Previous History - Received email from County Member Trudy Dean dated 07 Feb 08: Can I please report a complaint from residents about the state of Gilletts Lane, East Malling which runs between Rocks Road and Wateringbury Road. It is potholed and has a very uneven surface requiring attention. (Added by Pavinder). KHS previous comments - Feb 08: Pot-holes been attended to. Not cost affective for patching as road consistently poor throughout. Also, patching will only set back further any full scale resurfacing. Road passed to Programme Delivery to consider for programmed resurfacing. Mar 08:- Inspector continues to monitor for pot-holes. Apr 08 - Inspector continues to monitor. May 08 - No further work required at present, inspector will monitor as part of his scheduled safety inspections. Passed to Countywide Improvements with regard to possibility of resurfacing. June 08: Will be incorporated on future plan. Not this year or next. Email sent dated 25/11/08 to Trudy Dean - I have been advised that Gilletts Lane has been passed by our Community Operations Team to Countywide Improvements team (resurfacing team) for review again to possibly be considered for resurfacing in the future program. This review will be completed and available by early Jan 2009, I will let you know the outcome once information has been received.	ENQ - Enquiry Resolved		N	Work completed.

Parish Report

Enquiry Number	Cust Type Name	Logged Date	Street Location Details	Subject Name Service Name	Enquiry Desc	Enq Status Name	Job Start Date	O/S Flag	Latest Update
10201387	Parish Representative	04/12/2008	LUCKS HILL	Traffic Congest/Speed/Noise Traffic and Parking	Transferred from Parish Spreadsheet Ref T/EM/07/011- Previous History - A strong barrier is required on the sharp bend to protect pedestrians from vehicles failing to negotiate the bend, especially at the footway is well below road level. The rubber posts are regularly knocked down and it is only luck that no pedestrian was on the footway at the time. Khs previous comments - April update: I can confirm that this site has been highlighted by the crash cluster analysis and will be investigated in 2007/08. May 07 update: Crash remedial site visit has been undertaken. Improvements are being planned, prioritised and programmed for 2008/09. June 07 update: No further update. Aug 07 update: 40mph speed limit between East Malling & West Malling also being considered. Sept 07 update: Plans are being prepared for consultation. Oct 07 update: New speed limit plans have been sent back to consultants for modification. November: Speed limit plans are available. Have discussed with head office the current status of new speed limit review and trials. Will try to introduce speed limit with crash remedial measures for Lucks Hill bend next financial year (2008/09) January update: Ongoing awaiting new financial year 2008/09 to try and introduce speed limit with crash remedial measures. Mar 08: No further comments at present. Apr 08: Awaiting for 2008/09 programme to be confirmed soon. May 08: Programme confirmed by Highways Advisory Board and to go to JTB on 9th June 08. June 08: Land enquiries and land take issues are being considered. Aug/Sept 08: land negotiations commenced.	ENQ - Enquiry Resolved		N	Terry advised 17.02.09 that S Drenhan from Burton Knowles is handling this issue himself. Countywide improvements will implement an interim scheme designed by Andy Padgem - resurface, improve signing and cutting of vegetaiton. Parish updated at the last JTB. This enquiry is now resolved.
16202625	Parish Representative	25/06/2008	NEW HYTHE LANE Along the new hythe lane starting at the Larkfield Village Hall and finishing at the Larkfield lesuire centre.	z-Overgrown Hedge z-Vegetation	The Hedge is very overgrown and it is making it hard to walk along the path.	ENQ - Enquiry Resolved		N	Works have been passed to Contractor.
16203290	Parish Representative	27/06/2008	LUNSFORD LANE No. 41 Lunsford Lane, Larkfield, Kent ME20 6HN	z-Overgrown Hedge z-Vegetation	No. 41 Lunsford Lane, Larkfield, Kent ME20 6HN - Very Overgrown Vegetation on the footway	JO - Works Completed		N	

Parish Report

Enquiry Number	Cust Type Name	Logged Date	Street Location Details	Subject Name Service Name	Enquiry Desc	Enq Status Name	Job Start Date	O/S Flag	Latest Update
16204391	Parish Representative	03/07/2008	NEW HYTHE LANE Gullies both sides of the road are blocked. Laburnum Drive/New Hythe Lane, Larkfield Kent ME20 6LX & ME20 6PW	Blocked Gully Draining and Flooding	Blocked Gullies both sides of the road	JO - Works Completed		N	Job progressed
16207101	Parish Representative	16/07/2008	FIELDING DRIVE Path leading to tesco	z-Overgrown Hedge z-Vegetation	Footpath is overgrown and needs clearing.	JO - Works Completed		N	Landscape Services to carry out work
16209289	Parish Representative	25/07/2008	FIELDING DRIVE Alleyway to the rear of Fielding Drive, Larkfield - this path runs from the Redwing Close footbridge down through to Tesco	z-Weed Growth on highway/fway z-Vegetation	The overgrowth is terrible with the streetlights being obscured and indeed brambles, etc. This is a well used path and I would ask that some urgent action be taken to rectify the situation. Our PCSO Jo-Anne Tiller has also received numerous complaints from residents about the path which they are frightened to use for fear of getting injured.	JO - Works Completed		N	Work has been passed to contractor. Caller informed. Works completed in August 08.
16234672	Parish Representative	21/11/2008	LAVENDER ROAD outside property 44... ME19 6EE	Streetlight not working Street Lighting		JO - Works Completed	25/11/2008	N	faults raised ref 55037 JLAR009
16245598	Parish Representative	12/01/2009	AUSTEN WAY Pavement outside No. 11 Austen Way, Larkfield Kent ME20 6UL	Streetlight not working Street Lighting	Pavement outside No. 11 Austen Way, Larkfield Kent ME20 6UL Street light not working	ENQ - No Action Required		N	No action required as job 55629 is already raised on column JABM003 via the night patrol, target date 22/1/09. Am closing this csm as a duplicate as the job is in hand.