

| Enquiry Number | Street | Subject Name | Enq Status Name | Job Start / No Jobs | O/S Flag | Latest Update |
|-----------------------------------|-------------|--|---|--|----------|---|
| Cust Type Name | Logged Date | Location Details | Service Name | Enquiry Desc | | |
| 10203183 Parish Representative | 26/06/2009 | CASTLE WAY Castle Way adjacent to the bypass junction | Overgrown Grass Vegetation (see also Trees) | ENQ - Enquiry Reassigned Discussed at a site meeting on 19 June 09 with Leybourne Parish Council - 3. The grass verges at the end of Castle Way adjacent to the bypass junction, these have never been cut since the bypass was opened. Can we please investigate. | | Y |
| 10203193 Parish Representative | 26/06/2009 | CASTLE WAY adjacent to 73 Castle Way | Overgrown Grass Vegetation (see also Trees) | INSP - Inspected Discussed at a site meeting on 19 June 09 with Leybourne Parish Council - Grass verge adjacent (to 73 Castle Way) has not been cut this year why? Can we please investigate. FAO: Sara Hunter. | | Y Waiting for confirmation from Highway Definitions. This was a previous enquiry raised before new checking system introduced 24/07/09 |
| 10203291 Parish Representative | 10/07/2009 | OXLEY SHAW LANE The footpath to Oxley Shaw Lane adjacent to junction with Old Orchard Lane | Obstructing The Highway Vegetation (see also Trees) | ENQ - Enquiry Reassigned Discussed at a site meeting on 19 June 09 with Leybourne Parish Council - The footpath to Oxley Shaw Lane adjacent to junction with Old Orchard Lane the vegetation is encroaching / narrowing the footpath width. Can we please investigate. FAO: Sara Hunter. | | Y |
| 10203290 Parish Representative | 10/07/2009 | OXLEY SHAW LANE The footpath to Oxley Shaw Lane adjacent to junction with Lillieburn | Obstructing The Highway Vegetation (see also Trees) | ENQ - Enquiry Reassigned Discussed at a site meeting on 19 June 09 with Leybourne Parish Council - The footpath to Oxley Shaw Lane adjacent to junction with Lillieburn the vegetation is encroaching / narrowing the footpath width. Can we please investigate. FAO: Sara Hunter. | | Y |
| 10203344 Parish Representative | 16/07/2009 | OXLEY SHAW LANE The footpath between the top of Harvest Ridge around the 'Bomb Hole' to Oxley Shaw Lane, where it meets Oxley Shaw Lane | Obstructing Highway Trees | ENQ - Enquiry Reassigned Discussed at a site meeting on 19 June 09 with Leybourne Parish Council - The footpath between the top of Harvest Ridge around the 'Bomb Hole' to Oxley Shaw Lane, where it meets Oxley Shaw Lane there is a tree of which the lower branches encroach across the footpath and it was agreed over a year ago on a similar site visit that the canopy of the tree would be raised, which hasn't been done. Can we please investigate. FAO: Sara Hunter. | | Y Highways definition required for the area highlighted red on the attached plan. |
| 10203343 Parish Representative | 16/07/2009 | HARVEST RIDGE The footpath between the top of Harvest Ridge around the 'Bomb Hole' to Oxley Shaw Lane | Obstructing The Highway Vegetation (see also Trees) | ENQ - Enquiry Reassigned Discussed at a site meeting on 19 June 09 with Leybourne Parish Council - The footpath between the top of Harvest Ridge around the 'Bomb Hole' to Oxley Shaw Lane, overgrown vegetation reducing the path width. Can we please investigate. FAO: Sara Hunter. | | Y |
| 16280526 Parish Representative | 15/05/2009 | RECTORY LANE SOUTH Path between Baywell Open Space and Rectory Lane South is getting very over grown and needs strimming as a matter of urgency | Overgrown Weeds Vegetation (see also Trees) | INSP - Inspected Path between Baywell Open Space and Rectory Lane South is getting very over grown and needs strimming as a matter of urgency | | Y private vegetation hanging over obstructing |
| 16280528 Parish Representative | 15/05/2009 | CASTLE WAY A bollard has been knocked down on Castle Way in the 20 mph zone. Please arrange to have this fixed asap. | Side Of The Road Damaged Bollards-OthersNotInMiddleC | ENQ - Enquiry Acknowledged A bollard has been knocked down on Castle Way in the 20 mph zone. Please arrange to have this fixed asap. | | Y |

| Enquiry Number | Street | Subject Name | Enq Status Name | Job Start / No Jobs | O/S Flag | Latest Update |
|--------------------------------------|-------------|--|--|--|-------------|---|
| Cust Type Name | Logged Date | Location Details | Service Name | Enquiry Desc | | |
| 16285334 Parish Representative | 08/06/2009 | CASTLE WAY Leybourne - In Castle Way at two locations (1) First pinch point from A20, west side and (2) Second pinch point from A20, just south of the southern layby. | Side Of The Road Damaged Bollards-OthersNotInMiddleC | ENQ - Enquiry Reassigned Sent to Leybourne PC by Mr Graham Wootton of 13 Castle Way, Leybourne - "Two bollards have been damaged on chicanes which may not have been logged - (1) First pinch point from A20, west side. Bollard is not obviously in the vicinity. & (2) Second pinch point from A20, just south of the southern lay-by. S'bound has been hit pretty violently within the last twenty fours or so, bollard is at 45 degrees with the surrounding tarmac damaged." 05/06/09 | | Y new wooden bollard req and re setting of second bollard |