

Enquiry Number	Street	Subject Name	Enq Status Name	Job Start / No Jobs	O/S Flag	Latest Update
Cust Type Name	Logged Date	Location Details	Service Name	Enquiry Desc		
10201376 Parish Representative	04/12/2008	LUCKS HILL on bend	Request for New Chevron Signs-Chevron	ENQ - Enquiry Reassigned Transferred from Parish Spreadsheet Ref T/WM/07/049- advisory sign on bend - advising of maximum recommended speed rather than speed limit NB this was discussed with Mr Bateman at our meeting on 21.5.07 and he thought it a good idea. Previous history - Aug 07: This will be considered for inclusion in crash remedial measures. Sept 07 update: No further update. Oct 07 update: Crash remedial measures approved for 2008/09. November 07: New speed limit proposals are available and this should be included as part of crash remedial measures next financial year. Jan 08: No further update. Feb 08: This will be considered as part of crash remedial measure for the next financial year. Mar 08: No further comments at present. Apr 08: No change. Programme to be confirmed by Highways Advisory Board soon. May 08: Part of programme going to JTB on 9th June 08. June 08: Land take options are being considered. Aug/Sept 08: Formal land purchase is underway.		Y Terry will review upon his return from leave after the 17.08.09
10203192 Parish Representative	26/06/2009	ASHTON WAY central reservations to the Bypass from the Birling Roundabout to M20 junction 4 roundabout	Weeds Damage Private Property Vegetation (see also Trees)	ENQ - Enquiry Reassigned Discussed at a site meeting on 19 June 09 with Leybourne Parish Council - There is a lot of 'Ragwort' in the central reservations to the Bypass from the Birling Roundabout to M20 junction 4 roundabout locality which needs killing off. This is a hotspot due to horses in nearby location. Can we please investigate. FAO: Sara Hunter.		Y This area is mapped for ragwort treatment which is due to commence within 2 weeks 31/07/09 sh.
10203196 Parish Representative	26/06/2009	NORMAN ROAD	Obstructing The Highway Vegetation (see also Trees)	ENQ - Enquiry Reassigned The hedge along Norman Road is the responsibility of the Parish Council but the verge is not. Can KHS please investigate ownership as it is believed this is KHS. This issue was discussed at the recent site meeting with the Parish Council due to the nettles protruding onto the footway and causing the residents to walk on the carriageway . The Highway Inspector will investigate.		Y
10203223 Parish Representative	30/06/2009	WEST STREET Colonnade, West Street	Damaged Footpaths/Pavements	INSP - Inspection Required This has been passed to Operations to investigate repairs to the footway. Letter attached - view via links button.		Y
16253815 Parish Representative	04/02/2009	NORMAN ROAD West Malling - Norman Road/Alma Road Junction	Unclassified Draining and Flooding	INSP - Inspection Required "the surfacing at the junction of Norman Road/Alma Road, West Malling has been recently patched my members have reported this on several occasions as they felt that there was an underlying problem - surface water was draining beneath the patch which seemed worthy of further attention they would like to know please the outcome of your investigation of any underlying problem" 29/01/09		Y